


FIG. 1

FIG. 2






FIG. 3




FIG. 4
(PRIOR ART)





FIG. 5

FIG. 6



	$M_2 =$	$\begin{vmatrix} \exp(j\phi_2) & 0 & 0 & 0 & 0 & 0 & 0 & 0 \\ 0 & 1 & 0 & 0 & 0 & 0 & 0 & 0 \\ 0 & 0 & \exp(j\phi_2) & 0 & 0 & 0 & 0 & 0 \\ 0 & 0 & 0 & -1 & 0 & 0 & 0 & 0 \\ 0 & 0 & 0 & 0 & \exp(j\phi_2) & 0 & 0 & 0 \\ 0 & 0 & 0 & 0 & 0 & 1 & 0 & 0 \\ 0 & 0 & 0 & 0 & 0 & 0 & -\exp(j\phi_2) & 0 \\ 0 & 0 & 0 & 0 & 0 & 0 & 0 & 1 \end{vmatrix}$
164		
	$M_3 =$	$\begin{vmatrix} \exp(j\phi_3) & 0 & 0 & 0 & 0 & 0 & 0 & 0 \\ 0 & \exp(j\phi_3) & 0 & 0 & 0 & 0 & 0 & 0 \\ 0 & 0 & 1 & 0 & 0 & 0 & 0 & 0 \\ 0 & 0 & 0 & 1 & 0 & 0 & 0 & 0 \\ 0 & 0 & 0 & 0 & \exp(j\phi_3) & 0 & 0 & 0 \\ 0 & 0 & 0 & 0 & 0 & \exp(j\phi_3) & 0 & 0 \\ 0 & 0 & 0 & 0 & 0 & 0 & 1 & 0 \\ 0 & 0 & 0 & 0 & 0 & 0 & 0 & 1 \end{vmatrix}$
162		
	$M_4 =$	$\begin{vmatrix} \exp(j\phi_4) & 0 & 0 & 0 & 0 & 0 & 0 & 0 \\ 0 & \exp(j\phi_4) & 0 & 0 & 0 & 0 & 0 & 0 \\ 0 & 0 & \exp(j\phi_4) & 0 & 0 & 0 & 0 & 0 \\ 0 & 0 & 0 & \exp(j\phi_4) & 0 & 0 & 0 & 0 \\ 0 & 0 & 0 & 0 & 1 & 0 & 0 & 0 \\ 0 & 0 & 0 & 0 & 0 & 1 & 0 & 0 \\ 0 & 0 & 0 & 0 & 0 & 0 & 1 & 0 \\ 0 & 0 & 0 & 0 & 0 & 0 & 0 & 1 \end{vmatrix}$
160		

FIG. 7

$M_{2E} =$  170	$\exp(j\phi_2 + \psi_2)$	0	0	0	0	0	0	0
	0	1	0	0	0	0	0	0
	0	0	$\exp(j\phi_2 + \psi_2)$	0	0	0	0	0
	0	0	0	-1	0	0	0	0
	0	0	0	0	$\exp(j\phi_2 + \psi_2)$	0	0	0
	0	0	0	0	0	1	0	0
	0	0	0	0	0	0	$-\exp(j\phi_2 + \psi_2)$	0
	0	0	0	0	0	0	0	1
$M_{3E} =$  172	$\exp(j\phi_3 + \psi_3)$	0	0	0	0	0	0	0
	0	$\exp(j\phi_3 + \psi_3)$	0	0	0	0	0	0
	0	0	1	0	0	0	0	0
	0	0	0	1	0	0	0	0
	0	0	0	0	$\exp(j\phi_3 + \psi_3)$	0	0	0
	0	0	0	0	0	$\exp(j\phi_3 + \psi_3)$	0	0
	0	0	0	0	0	0	1	0
	0	0	0	0	0	0	0	1
$M_{4E} =$  174	$\exp(j\phi_4 + \psi_4)$	0	0	0	0	0	0	0
	0	$\exp(j\phi_4 + \psi_4)$	0	0	0	0	0	0
	0	0	$\exp(j\phi_4 + \psi_4)$	0	0	0	0	0
	0	0	0	$\exp(j\phi_4 + \psi_4)$	0	0	0	0
	0	0	0	0	1	0	0	0
	0	0	0	0	0	1	0	0
	0	0	0	0	0	0	1	0
	0	0	0	0	0	0	0	1

FIG. 8




FIG. 9




FIG. 10